



NOTES:

1. 555 operates with "RESET" = +V; 4040 operates with "RESET" = 0V
2. 4040 counts on lagging-edge signal which is why an inverter is used on the clock input

| | | |
|------------------------------------|-----------------------|-------------|
| microphone time-out | | |
| (retrofit for older radios) | | |
| Klaus S., WB9YBM | Rev 1.0 07/09/2018 | Page 1 of 1 |